


FIG.\_4




5/66 *1252* HAMMER OPERATING LEVER *1266* ZERO RETURN LEVER B SPRING 1244 OPERATING LEVER SPRING 1264 HEART CAM B - 1265 ZERO RETURN LEVER B SECOND WHEEL - 1251 OPERATING LEVER 1243 SWITCH LEVER A 1256 HAMMER JUMPER 1242 OPERATING LEVER 1201 START/STOP BUTTON *1241* COLUMN WHEEL JUMPER - 1202 RESET BUTTON 1261 HEART CAMA 1267 HEART CAM C 0 9 8 HEART CAM D 1270 CG 1/10-SECOND WHEEL 1232 **CG MINUTE AND HOUR WHEEL 1216** ZERO RETURN LEVER A 1262 ZERO RETURN LEVER C SPRING 1269 -SWITCH LEVER B 1257 -ZERO RETURN LEVER C 1268 -ZERO RETURN LEVER D SPRING 1272 -ZERO RETURN LEVER A SPRING *1263* HAMMER DRIVING LEVER 1254 ZERO RETURN LEVER D *1271* – INTERMEDIATE HAMMER SPRING 1255 1240a -1240b --**COLUMN WHEEL 1240 - -**CONTACT -RESET CIRCUIT INTERMEDIATE HAMMER 1253

































FIG.\_10










FIG.\_11







FIG.\_12









FIG.\_13









FIG.\_14













FIG.\_16


TP


FEB 1 3 2003

THADEWIN'S


























FEB 1 3 2003 22 / 66











FIG.\_26









































FIG.\_32






FIG.\_33







FIG.\_34








FIG.\_35









FIG.\_36













FIG.\_38





-






FIG.\_41







FIG.\_42





AUTOMATIC STOP POSITION MARK 1230a .

RESET BUTTON 1202

CHRONOGRAPH 1/10-SECOND HAND 1231

FIG.\_44

ORDINARY TIME INDICATOR 1110

ONE-SECOND INDICATOR 1230

DIAL 1002 ·









FIG.\_45

















FIG. 49







1201 START/STOP BUTTON

1267 HEART CAM C


HEART CAM D 1270




























FIG.\_55






FIG.\_56






FIG.\_57

1202









FIG.\_58









FIG.\_59









59 / 66






FIG.\_61













## P4469b, Serial No. 09/446,449 Customer No. 20178 63 / 66














FIG.\_67












FIG.\_69